

**Flood Control Project Maintenance
Levee Inspections**

2019 Channel Summary Report

Overall Unit and Item Ratings

Adin Community Service District

Ash Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Dry Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | N |
| | Encroachments | A |

Flood Control Project Maintenance**Unit Cover Sheet****2019 Channel Inspection Results****Adin Community Service District**

| Channel |
|-----------|
| Ash Creek |

| | |
|--------------------|--|
| Channel Rating | A |
| Date of Inspection | 7/24/2019 |
| DWR Inspector | Makar Sokol |
| Accompanied By | Mike Williams Adin Community Service District |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Main Street / Up

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 1 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_1_c_2012_1 | | | |
| Action/Comments | | | | |
| | | | | |

Photo 1 of 1 : CH_2019_NA0030_1_1_20190726_00008.jpg



View of the Ash Creek upstream of the Highway 299 bridge.

| | | | | |
|--|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 7 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_1_c_2012_7 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 3 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_1_c_2012_3 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Main Street / Up (cont)

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | N | Issue No. | 4 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Revetments | | | |
| DWR ID | DWR_NA0030_1_c _2012_4 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 5 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_5 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

Check Point / View

Main Street / Down

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 6 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_1_c_2012_6 | | | |
| Action/Comments | | | | |
| | | | | |

Photo 1 of 1 : CH_2019_NA0030_1_6_20190726_00009.jpg



Downstream view of Ash Creek from the Highway 299 bridge.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Main Street / Down (cont)

| | | | | |
|--|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 2 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_1_c_2012_2 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 8 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_1_c_2012_8 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | N | Issue No. | 9 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Revetments | | | |
| DWR ID | DWR_NA0030_1_c_2012_9 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Main Street / Down (cont)

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 10 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197770 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944100 ° |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_1_c_2012_10 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

Check Point / View

Ash Street / Up

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 11 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_1_c_2012_11 | | | |
| Action/Comments | | | | |
| | | | | |

Photo 1 of 1 : CH_2019_NA0030_1_11_20190726_00010.jpg



Upstream view of Ash Creek from the Ash Street crossing.

| | | | | |
|--|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 12 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_12 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |
| | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Ash Street / Up (cont)

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 13 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_13 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | N | Issue No. | 14 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Revetments | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_14 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 15 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_15 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Ash Street / Down

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 16 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_16 | | | |
| Action/Comments | | | | |
| | | | | |

Photo 1 of 1 : CH_2019_NA0030_1_16_20190726_00011.jpg



Downstream view of Ash Creek from the Ash Street crossing.

| | | | | |
|--|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 17 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_17 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

| | | | | |
|---|-------------------------------------|------------|----|---------------|
| Rating ** | M | Issue No. | 18 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_1_c_2012_18 | | | |
| Action/Comments | | | | |
| Inspector Comments: During low flows you can see the two gravel bars in channel. Monitor erosion during high flows. | | | | |
| | | | | |

Photo 1 of 1 : CH_2019_NA0030_1_18_20190522_00005.jpg



View of the gravel bars and moderate erosion on both banks.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Ash Street / Down (cont)

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 19 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Revetments | | | |
| DWR ID | DWR_NA0030_1_c_2012_19 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 20 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.197138 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.945271 ° |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_20 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

Check Point / View

Downstream limit/fish ladder & walkway / Up

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 31 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.954530 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_1_c_2012_31 | | | |
| Action/Comments | | | | |
| | | | | |

Photo 1 of 1 : CH_2019_NA0030_1_31_20190726_00012.jpg



Upstream view of Ash Creek from the weir.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Downstream limit/fish ladder & walkway / Up (cont)

| | | | | |
|--------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 32 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.954530 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_1_c_2012_32 | | | |

Action/Comments

Inspector Comments: No shoaling or sedimentation observed during the inspection.

No Photos

| | | | | |
|--------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 33 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.954530 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_1_c_2012_33 | | | |

Action/Comments

Inspector Comments: There is minor erosion along right side of the structure.

Photo 1 of 1 : CH_2019_NA0030_1_33_20190726_00014.jpg



View of the erosion along the right side of the weir.

| | | | | |
|--------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 34 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.954530 ° |
| Item | Revetments | | | |
| DWR ID | DWR_NA0030_1_c_2012_34 | | | |

Action/Comments

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Downstream limit/fish ladder & walkway / Up (cont)

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 35 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.954530 ° |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_35 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

Check Point / View

Downstream limit/fish ladder & walkway / Down

| | | | | |
|--|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 36 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.954530 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_36 | | | |
| Action/Comments | | | | |
| Inspector Comments: The channel is clear of vegetation & obstructions. | | | | |

Photo 1 of 1 : CH_2019_NA0030_1_36_20190726_00013.jpg



Downstream view of Ash Creek from the weir.

| | | | | |
|--|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 37 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.192990 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.954530 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_37 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Ash Creek | 1.00 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Downstream limit/fish ladder & walkway / Down (cont)

| | | | | |
|-----------------|-------------------------------------|------------|----|--------------|
| Rating ** | A | Issue No. | 38 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.192990 |
| Category | Rivers, Channels & Designated Flood | | | -120.954530 |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_38 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|----|--------------|
| Rating ** | A | Issue No. | 39 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.192990 |
| Category | Rivers, Channels & Designated Flood | | | -120.954530 |
| Item | Revetments | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_39 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|----|--------------|
| Rating ** | A | Issue No. | 40 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.192990 |
| Category | Rivers, Channels & Designated Flood | | | -120.954530 |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_1_c _ 2012_40 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2019 Channel Inspection Results****Adin Community Service District**

| Channel |
|-----------|
| Dry Creek |

| | |
|--------------------|--|
| Channel Rating | A |
| Date of Inspection | 7/24/2019 |
| DWR Inspector | Makar Sokol |
| Accompanied By | Mike Williams Adin Community Service District |

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Adin Street / Up

| | | | | |
|---|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 1 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_2_c_2012_1 | | | |
| Action/Comments | | | | |
| Inspector Comments: Keep vegetation in channel trimmed and low to the ground. | | | | |

Photo 1 of 1 : CH_2019_NA0030_2_1_20190726_00005.jpg



Upstream view of the Dry Creek from Adin Street.

| | | | | |
|--|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 2 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_2_c _ 2012_2 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 3 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_2_c_2012_3 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Adin Street / Up (cont)

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | N | Issue No. | 4 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Revetments | | | |
| DWR ID | DWR_NA0030_2_c_2012_4 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 5 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_2_c _ 2012_5 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

Check Point / View

Adin Street / Down

| | | | | |
|--|-------------------------------------|------------|---|---------------|
| Rating ** | M | Issue No. | 6 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_2_c_2012_6 | | | |
| Action/Comments | | | | |
| Inspector Comments: Peform vegetation management in channel. | | | | |
| | | | | |

Photo 1 of 1 : CH_2019_NA0030_2_6_20190726_00006.jpg



Downstream view of Dry Creek from Adin Street.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Adin Street / Down (cont)

| | | | | |
|--|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 7 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_2_c_2012_7 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | A | Issue No. | 8 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_2_c _ 2012_8 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|---|---------------|
| Rating ** | N | Issue No. | 9 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Revetments | | | |
| DWR ID | DWR_NA0030_2_c_2012_9 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Adin Street / Down (cont)

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 10 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.195370 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.943190 ° |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_2_c_2012_10 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

Check Point / View

Main Street / Up

| | | | | |
|---|-------------------------------------|------------|----|---------------|
| Rating ** | M | Issue No. | 11 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_2_c_2012_11 | | | |
| Action/Comments | | | | |
| Inspector Comments: Perform vegetation management in channel. | | | | |
| | | | | |

Photo 1 of 1 : CH_2019_NA0030_2_11_20190726_00007.jpg



Upstream view of Dry Creek from Main Street.

| | | | | |
|--|-------------------------------------|------------|----|--------------|
| Rating ** | A | Issue No. | 12 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.196350° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_2_c_2012_12 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |
| | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Main Street / Up (cont)

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 13 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_2_c _ 2012_13 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | N | Issue No. | 14 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Revetments | | | |
| DWR ID | DWR_NA0030_2_c _ 2012_14 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 15 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_2_c _ 2012_15 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Main Street / Down

| | | | | |
|---|-------------------------------------|------------|----|---------------|
| Rating ** | M | Issue No. | 16 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Vegetation & Obstructions | | | |
| DWR ID | DWR_NA0030_2_c _ 2012_16 | | | |
| Action/Comments | | | | |
| Inspector Comments: Perform vegetation management within the channel. | | | | |

Photo 1 of 1 : CH_2019_NA0030_2_16_20190726_00008.jpg



Downstream view of Dry Creek from Main Street.

| | | | | |
|--|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 17 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Shoaling / Sedimentation | | | |
| DWR ID | DWR_NA0030_2_c_2019_17 | | | |
| Action/Comments | | | | |
| Inspector Comments: No shoaling or sedimentation observed during the inspection. | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 18 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Erosion / Bank Caving | | | |
| DWR ID | DWR_NA0030_2_c_2012_18 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2019

Adin Community Service District

| Channel | Channel Length | Inspection Start/End | Inspector |
|-----------|----------------|--------------------------|-------------|
| Dry Creek | 0.20 | 07/24/2019 07/24/2019 | Makar Sokol |

Check Point / View

Main Street / Down (cont)

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | N | Issue No. | 19 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Revetments | | | |
| DWR ID | DWR_NA0030_2_c_2012_19 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | | |
|-----------------|-------------------------------------|------------|----|---------------|
| Rating ** | A | Issue No. | 20 | GPS Lat/Long |
| Issue Type + | Ma | Location * | | 41.196350 ° |
| Category | Rivers, Channels & Designated Flood | | | -120.944250 ° |
| Item | Encroachments | | | |
| DWR ID | DWR_NA0030_2_c_2012_20 | | | |
| Action/Comments | | | | |
| | | | | |

No Photos

| | | | |
|--|--|---|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain | + Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement |
|--|--|---|---|